



2013



17230



FI

Specifications

Processor head : **KOMATSU 365.1**

Crane : **CRH22**

Front Tires : **701X26,5**

Rear Tires : **710X26,5**

Tracks : **NO**

Extra features

It is in normal working condition and before export delivery we will carry out our complete Komatsu harvester service and function testing with needed repairs & fixings requiring appr. 2 weeks working time. At 5760 hours in December 2016 the following was done when the machine changed its owner:
*Komatsu Advanced mini-joysticks installed
*new feeding rollers installed
*new engine hood
And more recent repairs:
*crane's cylinders' sealings changed at 10000 h
*upper delimiting knife changed at 10000 h
*bottom feeding roller motor changed at 11000 h
*pump for working hydraulics changed at 11300 h
*PC X40 computer changed

in 2021 *side-feeding roller changed at
15000 h Additional equipment: *Used
transport support for the crane

Always available



info@celfor.com



+46 708 472 352
+351 915 274 979