



2017



14660



FI

Specifications

Crane : F145C 10m

Front Tires : 710x26,5

Rear Tires : 710x26,5

Tracks : no

Extra features

It is in normal working condition and before the export delivery we will do machine function testing with needed fixing, also change all oils, filters, and cleaners, adjust valves and nozzles, and change the MaxiExplorer language into Portuguese/Spanish.

Always available



info@celfor.com



+46 708 472 352
+351 915 274 979